

 [26-01-007G - ECM Update - DTC P019100 \(Campaign L07G\) \(posted 01.22.26\).pdf](#)

Genesis Motor America has launched Limited Coverage Campaign L07G Launch: ECM Software Update – DTC P109100

A. Affected Vehicles:

Certain 2022-2023MY G70 (IK) produced from 05/12/2021 – 10/16/2023

VIN Identification: Use the 'Vehicle Information' screen in WebDCS to verify "Warranty Start Date" and ensure the vehicle is within Emissions Warranty, observing mileage prior to any repair work.

B. Campaign Description:

Certain G70 (IK) vehicles equipped with the 2.0T-GDI engine may illuminate the Check Engine Light as a result of DTC P019100 (Fuel Rail Pressure Sensor Circuit Range/Performance).

Technical Service Bulletin (TSB) 26-01-007G provides instructions for updating the Engine Control Module (ECM).

C. Campaign Documents:

1. TSB 26-01-007G

A. Available on GenesisdealerUSA.com > Service > GMA Tech Info > Campaign

D. Action Required:

1. Confirm VIN eligibility for campaign via WebDCS. See "VIN Identification" note in part A.
2. **Follow TSB 26-01-007G** to perform the service procedure for the software update.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Genesis guests.

Thank you for your patience and understanding.

Warranty Campaign Team

Genesis Motor America