

GPOP - Issue Review System

Part Number: 52261481, 52271662

Part Description: SGW CALIBRATION SW

Issue Warning light on after replacing:
Description: Airbag (ORC) Lane control feedback (HALF) Customer will experience a warning light after replacing ORC DTCs:
B12C7, B12C8 The security gateway module software requires updating with the ORC/Half replacement.