

GPOP - Issue Review System

Part Number: 68651919A\$, 68651921A\$, 68732966A\$, 68732967A\$

Part Description: Ebooster

Issue C0582-00-BRAKE BOOSTER MOTOR "A" PHASE U-V-W CIRCUIT
Description: RANGE/PERFORMANCE C058A-00-BRAKE BOOSTER MOTOR "A" POSITION SENSOR CIRCUIT RANGE/PERFORMANCE C058E-00-BRAKE BOOSTER MOTOR "B" POSITION SENSOR CIRCUIT RANGE/PERFORMANCE After performing the diagnostic tests and determines to replace the Brake System Control Module (BSCM) also replace the EBooster. (Send back both Brake Electronic Control Unit and Hydraulic Control Unit for Engineering Analysis) To avoid potential charge-back, only use MOPAR approved brake fluid per the service manual. When filling the brake reservoir, use clean equipment and gloves during repair to avoid cross-contamination.