

On-car analysis list from January 14th, 2026
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	24-26	All	All	Oil Leak	Oil leak from Cylinder Head Cover (Untouched vehicles) (MY24 after engine serial DRK 154894)
	Taos	25-26	1.5 DNKA	All	P2080 Exhaust Gas Temperature Sensor Fault	Customer states MIL-on, fault P2080 present (Untouched vehicles) (Florida, Georgia, California vehicles only)
	Atlas, Cross Sport	24-25	All	All	Transmission error on dash/stuck in park. DTC P07E400 or P288B00 or P288800	Customer states transmission error on dash/unable to move shifter out of park
	Jetta	25	1.5 DNKA	All	DTC P0461 Stored In ECM	Customer states MIL-on (Untouched vehicles)
Electric	ID.4	25	All	All	DTC Active U122900 with symtom code 31949 stored in AW01 Front camera for driver assistance systems implausible	Customer states dynamic road sign assist error messages on instrument cluster and center display
Body	Tiguan	24	All	All	Striker Plate	Customer states wind noise and or water ingress (Untouched vehicles)
Chassis	Jetta GLI	25-26	All	MQ350	Clutch Pedal Noise/Clutch Pedal Pin Out of Place	Customer states there is a noise coming from the clutch pedal/clutch pedal pin out of place
	Golf R, GTI	24-25	All	All	Front Strut Noise	Customer states there is a noise coming from the front strut arae (Untouched vehicles)
	Atlas, Cross Sport	24-26	All	All	Front Outer CV Boot Leaking	Customer states there is a leak from the front of the vehicle (Untouched vehicles)