



# Service Bulletin

Bulletin No.: PIT6488

Date: February, 2026

## PRELIMINARY INFORMATION

**Subject: U1615 Setting In Power Steering Control Module**

| Brand:    | Model:    | Model Year: |    | VIN: |     | Engine: | Transmission: |
|-----------|-----------|-------------|----|------|-----|---------|---------------|
|           |           | from        | to | from | to  |         |               |
| Chevrolet | Blazer EV | 2024        |    | ALL  | ALL | BEV     | BEV           |

|                            |                                                                                                                     |
|----------------------------|---------------------------------------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                                                       |
| Additional Options (RPO)   | 9C1, 9C3                                                                                                            |
| Condition                  | During diagnosis of a vehicle U1615 may be found set current or in history in the K43 Power Steering Control Module |
| Cause                      | Engineering is currently investigating                                                                              |

### Correction

U1615 set in the K43 PSCM will not cause any issues with the operation of the vehicle.

Do not replace any parts in an attempt to correct U1615.

This PI will be converted to a bulletin when a determination is made by engineering.

|          |                       |
|----------|-----------------------|
| Version  | 1                     |
| Modified | 02/20/2026 — Created. |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.