

[U 26-01-021H - ECM Software Update \(LA16\)_\(Posted 02.23.26\).pdf](#)

Hyundai Motor America (HMA) has launched Limited Coverage Campaign LA16 for the ECM Software Update – DTC P05000, P050600!

A. Affected Vehicles:

- Certain 2026MY Palisade Hybrid (LX3 HEV) produced from 08/11/2025 - 09/30/2025
- VIN Identification: Use the 'Vehicle Information' screen in WebDCS to verify "Warranty Start Date" and ensure the vehicle is within New Vehicle Limited Warranty (NVLW), observing mileage prior to any repair work.

B. Campaign Description:

Certain Palisade Hybrid (LX3 HEV) vehicles equipped with the 2.5T-GDI HEV engine may set DTC P050500/P050600. **Technical Service Bulletin (TSB) 26-01-021H** provides instructions to perform a software update on the Engine Control Module (ECM) to resolve this condition.

- P050500 Idle Air Control System
- P050600 Idle Air Control System – RPM Lower than Expected.

C. Campaign Document(s):

1. TSB 26-01-021H

- a. Available on [Hyundaidealer.com](https://hyundaidealer.com) > Service > HMA Tech Info > Campaign

D. Action Required:

1. Confirm VIN eligibility for campaign via WebDCS. See 'VIN Identification' above.
2. **Follow TSB 26-01-021H** for service procedure to update the software.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.
Thank you for your patience and understanding.
Warranty Campaign Team
Hyundai Motor America