

## GPOP - Issue Review System

**Part Number:** 6ZM50TRMA\$

**Part Description:** SWITCH PARKING BRAKE

---

**Issue Description:** MP park brake light on and service park brake message on the cluster. The following DTCs can be present C10D0 - Electronic Park Brake System Failure C10ED - Electronic Park Brake Switch LED C10CD - Electronic Park Brake Switch - General Electrical Failure 1. Check there is no loose connection on the Park Brake Switch 2. Check there is no damage in connector D3863A, specially for the following circuits:  
- D497 - B65 Note:  
There is a reported issue on the harness from the Antilock Brake System (ABS), the harness is being damaged by a TCM bracket. If there is an issue found on the harness, DO NOT replace the Park Brake Switch. Repair instructions are documented in SOL S2508000069 3. If there are no issues found on the harness and switch is replaced. Please send the part to QEC