



Service Bulletin

Bulletin No.: PIC6649

Date: March, 2026

PRELIMINARY INFORMATION

Subject: Poor Active Grille Air Shutter Performance w/ DTC P059F Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	BOLT	2027		All	All	All	All

Involved Region or Country	North America
Condition	Customer may comment that they are getting an intermittent service High Voltage (HV) message. Technicians may find DTC P059F has set for an Active Grille Shutter Stuck Off condition.
Cause	The front fascia air shutter may also have snow/ice build-up, causing the shutter to not be able to calibrate/reach its travel angle as designed. Once build-up is gone, the message and DTC should disappear.

Correction

Do not replace parts.

Engineering is currently investigating the condition.

In the meantime, please advise customer they may continue to drive the vehicle.

This PI will be updated or replaced with TSB once a determination has been made.

Any snow/ice build-up, if present, should be cleared from front fascia air shutter, see image below.



7099336

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*4083608	Verify DTC P059F has set and clear snow/ice build-up	0.2 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	03/10/2026 - Created on

