



Service Bulletin

Bulletin No.: PIE0831A

Date: June, 2025

ENGINEERING INFORMATION

Subject: Engineering Information – Malfunction Indicator Lamp (MIL) Illuminated on Driver Information Center (DIC), DTC P0299 Set

This EI has been revised to end the need for gathering information from the field. Please discard PIE0831.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2024	2025	—	—	Equipped with 1.3L (RPO L3T)	—
Chevrolet	Trailblazer						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released April 22, 2025 Revised June 04, 2025 – Ended the need for gathering further information from the field.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.