

GPOP - Issue Review System

Part Number: 68203030A\$, 68203031A\$

Part Description: MODULE Door

Issue WL DDM/PDM Mirror Blindspot inoperative If DTC is present DTC B285F-15 Blind Spot
Description: Warning Light Control-Circuit Short to Battery or Open Before replacing DDM/PDM. Inspect connection on Mirror connector end. Perform electrical continuity test. After succesful continuity test. Via Witech perform hard reset and clear DTC.