



Service Bulletin

PRELIMINARY INFORMATION

Subject: Unwanted Stability Activation and/or C0710

Models: 2007 - 2013 Cadillac Escalade EXT
2007 - 2015 Cadillac Escalade Models
2007 - 2013 Chevrolet Avalanche
2007 - 2015 Chevrolet Silverado, Suburban, Tahoe
2007 - 2015 GMC Sierra Models, Yukon Models
With StabiliTrak (RPO JL4)

This PI was superseded to update Model Years. Please discard PIT4322F.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some owners may comment on unwanted Stability Activation and/or a Service Stability message. The EBCM may have set DTC C0710. This concern may occur if the vehicle's suspension system has been modified (Lift or Lowering Kits), wheelbase length modified (limo, etc...), wrong steering gear installed, and/or other than stock size wheels and tires installed.

Recommendation/Instructions

Before any in-depth diagnostics are performed, be aware that this concern could occur if the vehicle has been modified.

ADDITIONAL SI KEYWORDS:

ABS message tire wheel

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION