



Technical Service Bulletin

43 DTC U12B800 or P000000 is stored in the suspension control module

43 20 31 2058686/1 February 21, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi e-tron quattro	2019 – 2020	All	Not Applicable

Condition

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

One of the following DTCs may be stored in the suspension control module, J775 (address word 0074):

- **DTC U12B800** (ABS control unit implausible - passive/sporadic) with symptom code 15417397.

Or

- **DTC P000000** (passive/sporadic) with symptom code 15417397.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

If one of the DTCs described are stored in the suspension control module and no further DTCs are available in other control modules, then do not repair or replace. The DTCs listed above have no effects on the system characteristics. Clear DTC and release the vehicle.



Note:

If there are additional DTCs in the suspension control module, please follow the test plan to resolve the issues.



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles • G10 for CPO Covered Vehicles – Verify Owner • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4316		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 20 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2058686/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2058686) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.