



SERVICE BULLETIN

Classification:

EL15-003b

Reference:

NTB15-012b

Date:

May 13, 2020

2015 MURANO; DTC C1769 STORED AFTER BCM REPLACEMENT

APPLIED VEHICLE: 2015 Murano (Z52)

This bulletin is no longer applicable.

Discard previous versions of NTB15-012.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 3, 2015	NTB15-012	Original bulletin published
March 24, 2015	NTB15-012a	Title revised
May 13, 2020	NTB15-012b	Bulletin no longer applicable

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.