

Fault code B223209 is logged in the parking control unit

Topic number	LI54.65-P-071267
Version	1
Function group	54.65 Parking assist
Date	05-21-2020
Validity	Model series 118, 247, 177, 167, 253 facelift with SA code 235
Reason for change	
Reason for block	

Complaint:

Fault code B223209 is logged in the parking control unit.

Cause:

Software of parking control unit

Note:

Only valid if no EPS or ESP control unit fault code is logged.

Remedy:

Update software of parking control unit.

Note:

Do not replace the hardware of the parking control unit.

Symptoms

Communication/information / Assistance and warning systems / Parking assist / PARKTRONIC / Malfunction of displays / General

Control unit/fault code

Control unit	Fault code	Fault text
N62 - Parking system (PARK) (PARKMAN213) (GLS (167), GLC (253),GLE (167),A (177), CLA (118),B (247))	B223209	PARKTRONIC has a malfunction. There is a component fault.

Operation numbers/damage codes

XENTRY TIPS

Op. no.	Operation text	Time	Damage code	Note
54-0991	PROGRAM AND ENCODE PARKMAN CONTROL UNIT AFTER QUICK TEST		8251B 90	
54-0650	MAINTAIN 12V BATTERY			
54-1011	QUICK TEST			