

SSM 48916 - 2020 Escape/Corsair/Explorer/Aviator - DTC U0100 Stored In The ACM

Some 2020 Escape/Corsair/Explorer/Aviator vehicles may have diagnostic trouble code (DTC) U0100 stored in the audio front control module (ACM). This DTC will not cause observable conditions or warning indicators for the customer. If this DTC is detected during pre-delivery inspection (PDI) or while diagnosing unrelated conditions, it should be disregarded.

APPLICABLE VEHICLES

2020 CAR: TU U611A AVIATOR

2020 CAR: TF CX483N CORSAIR

2020 CAR: TC CX482N ESCAPE

2020 CAR: TZ U625A EXPLORER