

Subject: Engineering Information - Loss of Power, Hesitation and/or Stalls, DTCs P0172, P0299, P0101, P0506 and/or P1101 Set

This PI has been revised to end the need for information from the field. Please discard PIE0569A.

Brand:	Model:	Model Year:		Date Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2020	2020	December 01, 2019	EOP	Equipped with 1.5L Engine (RPO LYX)	-
GMC	Terrain						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released May 21, 2020 Revised June 03, 2020 – Revised to update the Correction. Revised July 15, 2020 – Ended the need for further information from the field.