



Technical Service Bulletin

48 ESC light is on, DTCs P060700 and/or C052800 are stored

48 20 90 2060682/1 September 16, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3 e-tron	2015-2018	All	Not Applicable

Condition

Customer states:

- The ESC light is on.

Workshop findings:

The following DTCs may be stored in the ABS/ESC control module:

- **DTC P060700** (Control module malfunction).
- **DTC C052800** (Steering angle sender – implausible signal).

Technical Background

After the ESC has been switched off, DTC P060700 might be stored in the ABS/ESC control module. Additionally, the steering angle sensor can be affected.

Production Solution

Not applicable.

Service

1. Proceed with the test plans for the DTCs (P060700 and C052800).
2. Then follow instructions described in the GFF and perform all necessary repairs according to ELSA.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.
--------------------	--



Technical Service Bulletin

Service Number:	Use applicable service number for repair performed		
Damage Code:	0040		
Labor Operations:	Labor Operations according to the service performed	See ELSA	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2060682/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA

Additional Information

All parts and service references provided in this TSB (2060682) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.