

Reference:

ITB03-066a

Date:

September 23, 2020

**VOLUNTARY SERVICE CAMPAIGN
IDLER PULLEY****CAMPAIGN I.D.#:** P3157**APPLIED VEHICLE:** 2002 Q45 (F50)**APPLIED VIN(S):** Vehicles built between: JNKBF01A*2M 000029 - 008654

Service Campaign ID # P3157 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P3157.
- Discard all previous versions of ITB03-066.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 3, 2003	ITB03-066	Original bulletin published
September 23, 2020	ITB03-066a	Bulletin no longer active