

STAR Case

Case Number: S1805000001 Rev C

Release Date: 09/25/2020

Symptom/Vehicle Issue: C2206 U140E DTCs Set After Replacement Of ABS Module

Discussion: If C2206 – Vehicle Configuration Mismatch and U140E Implausible Vehicle Configuration Data Received codes are set after an ABS module replacement.

2011 JS 2.4L for NAFTA markets (USA, Canada) 68096052AA is the current correct part ABS module. 68096052AB is for 3.6 applications.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Center Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via ECCI or eCONTACT ticket if no solution is found