



SERVICE BULLETIN

Classification:

EC20-027

Reference:

NTB20-084

Date:

November 30, 2020

INTELLIGENT KEY UNIT DTC P161D STORED IN THE ECM

APPLIED VEHICLES: 2021 Rogue (T33)
2020-2021 Sentra (B18)

SERVICE INFORMATION

DTC P161D (IMMOBILIZER) will not cause:

- The MIL to turn ON.
- The Remote Engine Start to become inoperative.
- The “No Key Detected” message to appear.
- An impact to any of the vehicle’s functions or performance.

If other DTCs are stored with P161D, perform the diagnosis and repair procedures, outlined in the ESM, for the other DTCs first.

- After the other DTCs have been resolved and P161D does not clear, proceed with the diagnosis and repair, outlined in the ESM, for DTC P161D.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 30, 2020	NTB20-084	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.