

If the vehicle has a Check Engine Light ON with DTC P2096 stored, update the PCM calibration with IDS version 99.01 or higher.

NOTE: This only applies to 2016MY CX-5.