

Fault Code U045A00 "Implausible Data Were Received From Control Unit 'Parking System'." Stored In Electric Power Steering Control Unit

Topic number	LI46.35-P-071804
Version	1
Function group	46.35 Electrical steering
Date	10-08-2020
Validity	Model 213 with SA code 801 model 238 with SA code 801

Reason for change

Reason for block

Complaint:

Fault code U045A00 "Implausible data were received from control unit 'Parking system'." stored in electric power steering control unit (N68).

Cause:

This fault code is set due to a parking system control unit (N62) service that is no longer required.

Remedy:

This fault code can be ignored. Steering functions without any restrictions.

This LI document will be updated as soon as there is optimized parking system control unit (N62) software.

Symptoms

Overall vehicle / Networking / Diagnosis/software / Current problems

Control unit/fault code

Control unit	Fault code	Fault text
N68 - Electrical power steering (ES) (EPS205_TK)	U045A00	Implausible data were received from control unit 'Parking system'. —
N68 - Electrical power steering (ES) (EPS205_ZF)	U045A00	Implausible data were received from control unit 'Parking system'. —

Validity

Vehicle	Engine	Transmission
E (213)	*	*
E (238)	*	*

