



Technical Service Bulletin

91 MIB3: DTC B1A06F1 (sym 1048589), B1A06F2 (sym 1048600) or U156C00 (sym 1850) are stored in the information module

91 21 62 2061934/1 January 19, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2022	All	MIB3
A6, A6 allroad, A6 Avant, S6, and RS6 Avant, A7, S7, RS 7, Q5, SQ5, Q7, SQ7, Q8, SQ8, RS Q8, Audi e-tron quattro, and Audi e-tron Sportback	2021 - 2022	All	MIB3
A4, S4, A4 allroad, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5 Cabriolet, RS 5 Sportback,	2020 - 2022	All	MIB3

Condition

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

One or more of the following DTC(s) may be stored relating to the information electronics control module 1, J794 (address word 005F):

- **DTC U156C00** (Ethernet_databus_gateway_timeout) with symptom code 1850.

Or

- **DTC B1A06F1** (a2b_bus_master_wrong_port_or_revers_wires) with symptom code 1048589.



Technical Service Bulletin

Or

- **DTC B1A06F2** (a2b_bus_master_reverse_wires_or_defective_node) with symptom code 1048600.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

1. The DTCs listed under condition are “Ghost DTCs”, meaning that they are entered erroneously in the control module.
2. Please ignore said DTCs. Do not run any test plans regarding them. Any repairs for those DTCs may be denied.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2061934) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.