

On-car analysis list from March 29th, 2021
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on (Must have P0087, P0148 and/or P053F fault codes) (Untouched vehicles)
Chassis	Jetta	20-21	All	All	Front End Noise	Customer states front suspension noise while driving (possibly while turning or going over bumps) (Untouched vehicles)
Electrical	Atlas, Atlas Cross Sport	19-21	All	All	MFI DTC U019900	Customer states "driver door contact switch error" and/or "electronic parking brake fault" in the MFI (Must have DTC U019900 in the ECM) (Untouched vehicles)
Body	Tiguan	19-21	All	All	Rear Tailgate Strut Broken/Loose/Detached	Customer states rear tailgate strut broken/loose/detached