

[Next Unread Message](#)**View Message**

Sent on	03	30	2021	Expires on	04	13	2021		
From	Parts and Service Division								
Subject	Request for Parts: 2018-2020 MDX & TLX V6 MIL On w/ DTC P0441 Stored								

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Information & Support Group (formerly TRS)
RE: Request for Parts: 2018-2020 MDX & TLX V6 MIL On w/ DTC P0441 Stored

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda Motor Co., Inc. (AHM) is searching for certain 2018-2020 MDXs (non-Hybrid) & TLX V6s with a client complaint of the Malfunction Indicator Light (MIL) on with the DTC P0441 (EVAP System Purge Flow Malfunction) stored. To better understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. MDX must be non-Hybrid.
2. DTC P0441 (EVAP System Purge Flow Malfunction) has been confirmed.
3. Mileage must be over 15,000 miles.
4. No repair has been attempted for this issue.

Action Required

If a vehicle matching the qualifiers above comes into your dealership, please e-mail Technical Information & Support (TIS – formerly TRS) at tis@ahm.honda.com. TIS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

1. Model Year (e.g. 2020)
2. Model Name (e.g. TLX)
3. Issue (e.g. Brake Judder)
4. VIN

E-Mail Body:

1. Dealer Number
2. Your Name
3. Best Phone Number to be Reached
4. Current Mileage

Thank you.