



SERVICE BULLETIN

Classification:

KS19-070A

Reference:

NTB19-118A

Date:

March 25, 2021

ALTIMA, KICKS AND VERSA SEDAN; DTC B26FE IN BCM AND KEY SYSTEM ERROR

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Discard all previous versions of this bulletin.

APPLIED VEHICLES: 2019-2020 Altima (L34)

Built on or before:

9/14/20 (Canton)

(11th VIN character = N, 1N4*L*****N*****)

8/14/20 (Smyrna)

(11th VIN character = C, 1N4*L*****C*****)

2019-2021 Kicks (P15)

Built on or before:

9/21/20

2019-2020 Versa Sedan (N18)

Built on or before:

8/19/20

APPLIED SYSTEM: Remote Engine Start (RES)**IF YOU CONFIRM**

- A "Key System Error" message is displayed on the combination meter,

And

- DTC B26FE (IPDM - KEY SYSTEM ERROR) is stored in the BCM.

ACTION

Replace the Intelligent Power Distribution Module (IPDM E/R).

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Replace the IPDM E/R.
 - For IPDM E/R replacement, refer to the ESM section below.
 - **ELECTRICAL & POWER CONTROL > POWER CONTROL SYSTEM > IPDM E/R > REMOVAL AND INSTALLATION > IPDM E/R.**

PARTS INFORMATION

DESCRIPTION	MODEL	PART NUMBER	QUANTITY
Control Unit Assy (IPDM E/R)	Altima, Versa Sedan	284B7-6CA3A	1
	Kicks	284B7-5RF3B	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace the IPDM E/R	(1)	RD21AA	ZE	32	(2)

- (1) Reference the electronic parts catalog and use the IPDM E/R (284B7-*****) as the Primary Failed Part (PFP).
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated Flat Rate Time.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 13, 2019	NTB19-118	Original bulletin published
March 25, 2021	NTB19-118A	Changes made throughout bulletin