



SERVICE BULLETIN

Classification:

DA18-001A

Reference:

NTB18-008A

Date:

March 24, 2021

ADAS SYSTEM DTC C1A03, C1A04, AND/OR C1B01 SERVICE INFORMATION

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2017 – 2018 Rogue (T32) 2017 – 2018 Murano (Z52)
2017 – 2018 Rogue Sport (J11) 2017 – 2018 Sentra (B17)
2017 – 2018 Armada (Y62) 2017 – 2018 Altima (L33)
2017 – 2018 Pathfinder (R52) 2017 – 2018 Maxima (A36)

**This bulletin applies to the above vehicles equipped with Automatic
Emergency Braking (AEB) or Forward Emergency Braking (FEB).**

SERVICE INFORMATION

If the following ICC/ADAS codes are stored, make sure to follow the diagnostic procedures in the Electronic Service Manual (ESM) before replacing any parts.

C1A03 – VEHICLE SPEED SENSOR

- The diagnostic procedure in the ESM includes **check and, if needed, repair for ABS DTCs before replacing ADAS components.**
- If repairs are performed for the ABS system; when compete, perform DTC Confirmation Procedure again before doing any additional repairs.

C1A04 – ABS/TCS/VDC SYSTEM

- The diagnostic procedure in the ESM includes **check and, if needed, repair for ABS DTCs before replacing ADAS components.**
- If repairs are performed for the ABS system; when compete, perform DTC Confirmation Procedure again before doing any additional repairs.

C1B01 CAM AIMING INCOMP

- The diagnostic procedure in the ESM includes **check and, if needed, repair for LANE CAMERA DTCs before replacing ADAS components.**
- LANE CAMERA DTC may require adjustment of the lane camera.
- If repairs/adjustments are performed for the Lane Camera; when compete, perform DTC Confirmation Procedure again before doing any additional repairs.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
February 1, 2018	NTB18-008	Original bulletin published
March 24, 2021	NTB18-008A	Classification number updated