



Preliminary Information

PIP5783 DTC P026C Under Investigation.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2021	All	All	6.6 L5P	All
GMC	Sierra 2500/3500	2021	All	All	6.6 L5P	All

Involved Region or Country:	North America, Middle East, Israel, Palestine
Condition:	A dealer technician may find DTC P026C set as current or in history.
Cause:	Under investigation.

Correction:

If you encounter a vehicle with DTC P026C set as current or history clear the trouble code, advise the customer the concern is currently under investigation by GM Engineering.

Clear the DTC using the scan tool and release the vehicle to the customer.

This Preliminary Information (PI) will be updated once more information becomes available.

Version History

Version	1
Modified	2/26/2021 - Created.

