



Preliminary Information

PIC6435 Service Adaptive Headlamp Message, Lin Bus DTC U1523 Setting After Right Headlamp Replaced

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XTS	2013 - 2019	All	All	All	All

Involved Region or Country	North America
Condition	Service Adaptive Headlamp message with DTC U1523 setting after right headlamp replacement.
Cause	Part Issue

Correction:

Engineering is aware of the concern and looking into a resolution. Contact Partech for further information.

Version History

Version	1
Modified	03/31/2021 - Created on.



GENERAL MOTORS