

SSM 49744: 2020-2021 Escape/2021 Bronco Sport - 1.5L - Low Oil Pressure Warning With DTC P0524

Some 2020-2021 Escape/2021 Bronco Sport vehicles equipped with a 1.5L engine may exhibit a low oil pressure warning with diagnostic trouble code (DTC) P0524. The Workshop Manual (WSM) Sections 303-14, 303-00, and 413-01 have been updated with new information to aid in diagnosis of the low oil pressure warning and DTC P0524.

Vehicles:

2021 Bronco Sport (CX430) (HD)

2020-2021 Escape (CX482) (TC)