

Reference:

ITB10-015B

Date:

June 16, 2021

VOLUNTARY SERVICE CAMPAIGN 2010 G37 WITH NAVI; RADIO SEEK FUNCTION

CAMPAIGN ID #: P0308

APPLIED VEHICLE: 2010 G37 Sedan, Coupe, & Convertible (V36, CV36, & HV36)

Service Campaign ID # P0308 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P0308.
- Discard all previous versions of ITB10-015.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 24, 2011	ITB10-015	Original bulletin published
February 2, 2011	ITB10-015A	SERVICE PROCEDURE updated
June 16, 2021	ITB10-015B	Bulletin no longer active