

SSM 49954 - 2018-2021 EcoSport - DTC U0155 Stored In the Anti-lock Brake System (ABS) Module

Some 2018-2021 EcoSport vehicles may have diagnostic trouble code (DTC) U0155 stored in the ABS module. This DTC will not cause observable conditions or warning indicators for the customer. If this DTC is detected while diagnosing unrelated conditions, it should be disregarded.

APPLICABLE VEHICLES

2018 - 2021 CAR: BW B515A ECOSPORT INDIA