

Reference:

ITB11-031B

Date:

July 21, 2021

VOLUNTARY SERVICE CAMPAIGN
2011 QX56; VEHICLE DYNAMIC CONTROL (VDC) REPROGRAMMING

CAMPAIGN ID #: P1217**APPLIED VEHICLE:** 2011 QX56 (Z62)

Service Campaign ID # P1217 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P1217.
- Discard all previous versions of ITB11-031.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 12, 2011	ITB11-031	Original bulletin published
May 25, 2011	ITB11-031A	INTRODUCTION revised
July 21, 2021	ITB11-031B	Bulletin no longer active