

**SERVICE CAMPAIGN BULLETIN**

Reference:

NTB11-057A

Date:

July 28, 2021

**VOLUNTARY SERVICE CAMPAIGN
2009 cube® VEHICLE NO START DUE TO ELECTRONIC
STEERING COLUMN LOCK (ESCL)****CAMPAIGN ID #:** P1225**APPLIED VEHICLES:** 2009 cube® (Z12) equipped with Intelligent Key**Service Campaign ID # P1225 is no longer active.**

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P1225.
- Discard all previous versions of NTB11-057.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
June 23, 2011	NTB11-057	Original bulletin published
July 28, 2021	NTB11-057A	Bulletin no longer active