

On-car analysis list from August 19th, 2021
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta, Golf	21	1.4T (DGXA)	All	MIL-on P013E	Customer states MIL-on with P013E in the ECM (repeat cases accepted)
	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on with P0087 P0148 P053F in the ECM (Untouched vehicles)
Chassis	Jetta, GTI, Golf	21	All	Manual Only	Clutch Pedal Noise (8/16/2021)	Customer states noise during clutch pedal operation (Untouched vehicles) (only looking for clutch pedal related noises)
Body	Atlas, Atlas Cross Sport	21	All	All	Cable Disconnected	Customer states hood release inoperative. (Untouched vehicles)
	Atlas, Atlas Cross Sport	20-21	All	All	HVAC Temperature flap	Customer states there is a popping/clicking noise while operating temperature settings
Other	Jetta, Golf, Jetta SportWagen, Golf SportWagen, Beetle, Beetle Convertible	09-14	2.0 TDI (CBEA and CJAA)	All	Gen 1 TDI	Customer states MIL-on with P0401 (TSB 01-18-13 2034898 must be applicable and completed before calling VW Helpline)