

SSM 50074 - 2020-2021 F-Super Duty - Equipped With Electronic Steering Actuator - Various Steering Fault Messages - DTC C1B00 - Built On Or Before 12-Apr-2021

Some 2020-2021 F-Super Duty vehicles equipped with an electronic steering actuator and built on or before 12-Apr-2021 may exhibit various steering fault messages with diagnostic trouble code (DTC) C1B00 stored in the power steering control module (PSCM). To correct the condition, reprogram the PSCM using the latest software level of the appropriate Ford diagnostic scan tool. For claiming, use causal part 3G568 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2020 - 2021 TRUCK: FE P558N SUPER DUTY