



Preliminary Information

PIT5845 Adaptive Cruise Inoperative with Adaptive Cruise Control Temporarily Unavailable Message and code U0422

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XT5	2019 - 2021	All	All	All	All
Cadillac	XT6	2019 - 2021	All	All	All	All
Chevrolet	Blazer	2019 - 2021	All	All	All	All
GMC	Acadia	2019 - 2021	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	KSG Adaptive Cruise Control
Condition	Customer may comment that the adaptive cruise is inoperative with adaptive cruise control temporarily unavailable message and DTC U0422 in the EBCM. The regular cruise may work when this happens.
Cause	Concerns with the front seatbelts can cause the DTC U0422 in the EBCM and an adaptive cruise control concern.

Correction:

Use GDS 2 to monitor the SDM data and look at both the driver's and passenger's seat belt status. They should change between buckled and unbuckled. If they do not change or don't read buckled or unbuckled, diagnose the seatbelt concern prior to the adaptive cruise concern.

Version History

Version	1
Modified	06/25/2021 - Created on.



