

On-car analysis list from November 9th, 2021
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on with P0087 P0148 P053F in the ECM (Untouched vehicles)
	Taos	21-22	All	All	Misfire	Customer states MIL-on with any combination of P0300, P0301, P0302, P0303, P0304, P1D74 and/or P1D75 in the ECM (Codes must be in the ECM, but misfire MUST BE INACTIVE)
	Atlas, Atlas Cross Sport	21	All	All	Heat Shield Rattle	Customer states rattle noise from the underbody heat shields
Chassis	Atlas, Atlas Cross Sport	21	All	All	Front Suspension Noise	Customer states noise from front suspension (Untouched vehicles) Must be after VIN break MC537933 (Atlas) or MC201092 (Atlas Cross Sport)
	Jetta, GTI, Golf	21	All	Manual Only	Clutch Pedal Noise	Customer states noise during clutch pedal operation (Untouched vehicles) (only looking for clutch pedal related noises)
Electric	Atlas, Atlas Cross Sport	21-22	All	All	Airbag Light	Customer states airbag light on (Untouched vehicles) (Must contain B100B1B and/or B100A1B in the airbag module) (Vehicles produced after 12/10/2020)
	Passat	19-21	All	All	ODIS Communication	Customer states no crank/no start. Vehicle is towed in. (Untouched vehicles)