



Technical Service Bulletin

27 DTC P1D6C00 is stored in the gateway

27 21 39 2064846/1 November 17, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi e-tron GT, Audi RS e-tron GT	2022	All	Not Applicable

Condition

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTC is stored in the gateway, J533 (address word 0019) as sporadic/intermittent:

- **DTC P1D6C00** (12V battery faulty).

Technical Background

A software error occurs in the gateway, J533 (address word 0019).

The DTC does not affect the operation of the vehicle and no action is required.

Production Solution

Not applicable.

Service

The DTC does not affect the operation of the vehicle and no action is required.

Please do not attempt any repairs.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (2064846) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.