



Preliminary Information

PIT4322M Unwanted Stability Activation and/or C0710

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade EXT	2007 - 2013	All	All	All	All
Cadillac	Escalade	2007 - 2022	All	All	All	All
Chevrolet	Avalanche	2007 - 2013	All	All	All	All
Chevrolet	Silverado	2007 - 2022	All	All	All	All
Chevrolet	Suburban	2007 - 2022	All	All	All	All
Chevrolet	Tahoe	2007 - 2022	All	All	All	All
GMC	Sierra	2007 - 2022	All	All	All	All
GMC	Yukon	2007 - 2022	All	All	All	All

With StabiliTrak

Supersession Statement:

This PI was superseded to update Model Years. Please discard PIT4322L.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Some owners may comment on unwanted Stability Activation and/or a Service Stability message. The EBCM may have set DTC C0710. This concern may occur if the vehicle’s suspension system has been modified (Lift or Lowering Kits - refer to latest version of [21-NA-222](#) for further information), wheelbase length modified (limo, etc...), wrong steering gear installed, and/or other than stock size wheels and tires installed.

Recommendations / Instructions

Before any in-depth diagnostics are performed, be aware that this concern could occur if the vehicle has been modified.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Additional SI Keywords

ABS message tire wheel



GENERAL MOTORS