

SSM 50503 - 2020-2022 F-Super Duty - 6.7L - Cooling Fan Noisy And/Or Runs Continuously

Some 2020-2022 F-Super Duty vehicles equipped with a 6.7L engine may exhibit a cooling fan with excessive noise or stays on continuously. The Workshop Manual (WSM), Section 303-03 Engine Cooling > Diagnosis and Testing > Cooling Fan Control, pinpoint test (PPT) AH has been updated to improve diagnostics and reduce unnecessary cooling fan clutch replacements.

APPLICABLE VEHICLES
2020 - 2022 TRUCK: FE P558N SUPER DUTY

ERROR: syntaxerror
OFFENDING COMMAND: --nostringval--

STACK:

```
(      ~      ~      ~      ~      6      N      f      ~      fi      fi      ~      b      "      '
)
(      ~      i      #      i      #      i      #      i      #      i      #      i      #      i      #      i      #      i      #      i      #      Z      <      D      a      D      a      D      a      D      a      D
)
(      cvt      „p      5      <      ...fpgm~      7      h      +glyph»]l      P      `      headłMy-      6hhea      >      k
)
-mark-
/sfnts
```