

SSM 50549 - 2018-2020 F-150, 2017-2022 F-Super Duty And 2016-2022 F-650/F-750 - Diesel Engine - DTC P0000 Stored In The PCM

Some 2018-2020 F-150, 2017-2022 F-Super Duty and 2016-2022 F-650/F-750 vehicles equipped with a diesel engine may exhibit diagnostic trouble code (DTC) P0000 stored in the powertrain control module (PCM) after an on-demand self test. This DTC is due to a processing error in the PCM as a result of on-demand self testing. P0000 is an invalid DTC that will not illuminate the malfunction indicator lamp (MIL) and no repairs should be performed.

APPLICABLE VEHICLES

2018 - 2020 TRUCK: FC P552N F-150

2016 - 2019 TRUCK: BC H567N MEDIUM TRUCK

2021 - 2022 TRUCK: BC H567N MEDIUM TRUCK

2016 - 2019 TRUCK: BC H567N MEDIUM TRUCK

2021 - 2022 TRUCK: BC H567N MEDIUM TRUCK

2016 - 2019 TRUCK: BC H567N MEDIUM TRUCK

2021 - 2022 TRUCK: BC H567N MEDIUM TRUCK

2017 - 2022 TRUCK: FE P558N SUPER DUTY