

Subject		Market
2022 Tundra - DTC P17A39E Set		USA
Service Category	Section	
Drivetrain	Axle/Differential	
Applicability		
2022 Tundra		

APPLICABLE VEHICLES

2022

Tundra

CONDITION

DTC P17A39E is currently under investigation.

RECOMMENDATIONS

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references