

Subject		Market
2022 Tundra - MIL ON W/DTCs for Turbocharger system (V35A)		USA
Service Category	Section	
Engine/Hybrid System	Engine Mechanical	
Applicability		
Tundra		

APPLICABLE VEHICLES

2022

Tundra

CONDITION

Some 2022 MY Tundra vehicles, may experience a MIL ON condition with one or more of the following DTC(s):

- DTC P024300 Turbocharger/Supercharger Wastegate Actuator "A"
- DTC P024700 Turbocharger/Supercharger Wastegate Actuator "B"
- DTC P25B372 Turbocharger/Supercharger Wastegate "A" Actuator Stuck Open
- DTC P25B473 Turbocharger/Supercharger Wastegate "A" Actuator Stuck Closed
- DTC P25B572 Turbocharger/Supercharger Wastegate "B" Actuator Stuck Open
- DTC P25B673 Turbocharger/Supercharger Wastegate "B" Actuator Stuck Closed
- DTC P02351C Turbocharger/Supercharger Boost Sensor "A" Circuit Voltage Out of Range

RECOMMENDATIONS

Please follow the applicable repair manual process per DTC.

NOTE:

- Turbocharger sub-assembly is not a serviceable part.
- Do not attempt to adjust or repair the turbocharger sub-assembly or its constituent components.
- If the turbocharger sub-assembly is found to be defective, it must be replaced.

LINK REFERENCES

- [V35A-FTS \(INTAKE / EXHAUST\): TURBOCHARGER: PRECAUTION; 2022 MY Tundra \[11/2021 - ???????\]](#)
- [V35A-FTS \(INTAKE / EXHAUST\): TURBOCHARGER: ON-VEHICLE INSPECTION; 2022 MY Tundra \[11/2021 - ???????\]](#)
- [V35A-FTS \(INTAKE / EXHAUST\): TURBOCHARGER: REMOVAL; 2022 MY Tundra \[11/2021 - ???????\]](#)
- [V35A-FTS \(INTAKE / EXHAUST\): TURBOCHARGER: INSPECTION; 2022 MY Tundra \[11/2021 - ???????\]](#)
- [V35A-FTS \(INTAKE / EXHAUST\): TURBOCHARGER: INSTALLATION; 2022 MY Tundra](#)



Subject

**2022 Tundra - MIL ON W/DTCs for Turbocharger
system (V35A)**

Market

USA

Applicability

[\[11/2021 - ???????\]](#)