

Reference:

ITB01-017B

Date:

March 23, 2022

**VOLUNTARY SERVICE CAMPAIGN
2002 Q45; FUEL TANK SLOW FILL****CAMPAIGN ID #:** P1109**APPLIED VEHICLES:** 2002 Q45 (F50)**APPLIED VINS:** Vehicles built between: JNKBF01A*2M000098 - 002244

CAMPAIGN ID # P1109 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P1109.
- Discard all previous versions of ITB01-017.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 11, 2001	ITB01-017	Original bulletin published
May 1, 2001	ITB01-017a	SERVICE PROCEDURE revised
March 23, 2022	ITB01-017B	Bulletin no longer active