



SERVICE CAMPAIGN BULLETIN

Reference:

NTB10-068F

Date:

March 30, 2022

VOLUNTARY SERVICE CAMPAIGN NISSAN NAVIGATION SOFTWARE UPDATE

CAMPAIGN ID #: P0337

APPLIED VEHICLES: 2010 Altima Sedan, Coupe, and Hybrid (L32, CL32, and L32HV)
2010 Maxima (A35)
2010 370Z Coupe and Roadster (Z34 and HZ34)
2011 GT-R (R35)

Service Campaign ID # P0337 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P0337.
- Discard all previous versions of NTB10-068.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 9, 2010	NTB10-068	Original bulletin published
August 6, 2010	NTB10-068a	APPLIED VEHICLES revised and changes made on pages 2, 3, 11, 12, and 13
March 23, 2011	NTB10-068b	Reference to NTB10-125 added
August 18, 2011	NTB10-068c	Bulletin superseded by NTB11-073
October 4, 2011	NTB10-068d	Changes made on pages 2-14
January 28, 2013	NTB10-068e	Changes made throughout
March 30, 2022	NTB10-068F	Bulletin no longer active