

Reference:

ITB10-068A

Date:

April 6, 2022

COPYRIGHT © NISSAN NORTH AMERICA, INC.

VOLUNTARY SERVICE CAMPAIGN
2011 G25; ENGINE CONTROL MODULE (ECM) REPROGRAMMING

CAMPAIGN ID #: P0385
APPLIED VEHICLES: 2011 G25 (V36)

Service Campaign ID # P0385 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P0385.
- Discard all previous versions of ITB10-068.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 4, 2010	ITB10-068	Original bulletin published
April 6, 2022	ITB10-068A	Bulletin no longer active