

Reference:

ITB11-046B

Date: COPYRIGHT© NISSAN NORTH AMERICA, INC.

April 6, 2022

VOLUNTARY SERVICE CAMPAIGN CALL WAITING FUNCTION NAVIGATION UPDATE

CAMPAIGN ID #: P1235

APPLIED VEHICLES:

- 2010 G37 Convertible (HV36)
- 2010 G37 Coupe (CV36)
- 2010 G37 Sedan (V36)
- 2011 – QX56 (Z62)
- 2010 – 2011 FX35/50 (S51)
- 2010 – 2011 EX35 (J50)
- 2011 – 2012 M37/56 (Y51)
- 2012 M35h Hybrid (Y51HV)

Service Campaign ID # P1235 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P1235.
- Discard all previous versions of ITB11-046.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
August 31, 2011	ITB11-046	Original bulletin published
January 28, 2013	ITB11-046a	Changes made throughout
April 6, 2022	ITB11-046B	Bulletin no longer active