



TECHNICAL SERVICE BULLETIN

Classification:

AN22-011

Reference:

NTB22-034

Date:

April 28, 2022

ROCKFORD PREMIUM AUDIO KIT DTCS STORED IN INFOTAINMENT HEAD UNIT

APPLIED VEHICLES: 2018-2022 Kicks (P15)
APPLIED GRADES: SV and SR
APPLIED SYSTEMS: Only on Display Audio without Bose

SERVICE INFORMATION

The following DTCs may be stored in the infotainment head unit of an **APPLIED VEHICLE** that a Rockford Premium Audio Kit (dealer/port accessory, Figure 1 on page 2) has been installed. These DTCs do not indicate a malfunction of the system, and shall be ignored.

- **B130B-13** – (Rear RH speaker -or- Rear Right Speaker Open Load)
- **B130D-13** – (Front RH speaker -or- Front Right Speaker Open Load)
- **B130F-13** – (Front LH speaker -or- Front Left Speaker Open Load)
- **B1311-13** – (Rear LH speaker -or- Rear Left Speaker Open Load)

NOTE:

- These DTCs will all appear together and cannot be permanently erased.
- If sound is not coming out of one or more speakers, refer to the ESM for additional diagnostic information.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.



GENUINE PARTS

INSTALLATION INSTRUCTIONS

DESCRIPTION: Rockford Premium Audio Kit

APPLICATION: Kicks

PART NUMBER(S)

REQUIRED FOR T99U4-5RL0A Rockford Premium Audio Kit

INSTALLATION: T99U4-5RL0C

KIT CONTENTS:




Figure 1

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 28, 2022	NTB22-034	Original bulletin published