



Service Bulletin

Bulletin No.: 22-NA-044

Date: February, 2022

TECHNICAL

Subject: Check Engine MIL Illuminated in DIC Set by Body Control Module with DTC P0607

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2021	2022	—	—	—	—
Cadillac	CT4	2020	2022				
	CT5						
	Escalade	2021	2022				
	Escalade ESV						
Chevrolet	Corvette	2021	2022				
	Tahoe						
	Suburban						
GMC	Yukon	2021	2022				
	Yukon XL						

Involved Region or Country	North America, Europe, Australia/New Zealand
Condition	Some customers may comment on a check engine light illuminated on the DIC. Technicians may find DTC P0607 in the body control module (BCM) set current or in recent history.
Cause	The cause of the condition may be an internal BCM software anomaly can inadvertently set DTC P0607 and set the check engine light.
Correction	Do not replace the BCM. Engineering is currently investigating a root cause. 1. Clear all DTCs and perform a global battery reset. 2. Ensure all modules have powered down. 3. Start the vehicle and ensure the check engine light does not return.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2888468*	Global Battery Reset and Code Clear	0.6 hr
*This is a unique Labor Operation for bulletin use only.		

Version	1
Modified	Released February 23, 2022

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION